



The College of Naturopaths of Ontario

Inspection Committee Report

Revibe TO
2290 Dixie Road,
Mississauga, ON
L4Y 1Z4

Following a review of the Inspector's Report and all other documentation pertaining to the Part I New Premises inspection of the above premises conducted on October 14, 2022 the Inspection Committee has issued an outcome of a pass with conditions.

No Registrant¹ of the College of Naturopaths of Ontario is permitted to perform IVIT procedures at Revibe TO unless and until the premises receives a pass or a pass with conditions that do not restrict the performance of IVIT procedures (Section 33(8) Ontario Regulation 168/15).

Condition

The condition is:

1. As per Inspection Program Requirement 2.1.4: Laminar air flow hood is in place for premises where compounding for IVIT is conducted.

The Committee requires that a laminar air flow hood must in place prior to being allowed to begin to perform the procedures of compounding for and administering by IVIT.

Recommendation

When Inspection Program Requirements are partially met and do not warrant a condition being placed on the premises, the Inspection Committee makes recommendations to the premises.

The Committee makes the following recommendation:

i) As per Inspection Program Requirement 3.5: The refrigerator used for IVIT drugs/substances is at the correct temperature (2-8 °C) and monitored with a thermometer that records maximum and minimum temperatures and includes an external visual readout.

The Committee recommends that a thermometer be placed inside the refrigerator that allows for external monitoring of the refrigerator temperature and also records the maximum and minimum temperatures.